

**REPAIR OR REFURBISHING OF TELEPHONE EQUIPMENT  
SP-09-0016**

**Vendor Information:**

Telesource Services, LLC  
1450 Highwood East  
Pontiac, MI 48340

Contact: Mike Szymanski  
800-525-4300 [mikes@tsrc.com](mailto:mikes@tsrc.com)

**Buyer Information**

Renee Gates 501-371-6066, [renee.gates@dfa.state.ar.us](mailto:renee.gates@dfa.state.ar.us)

**CONTRACT EXPIRES:** SEPT. 20, 2011

**DROP OF ADDRESS FOR REPAIRS**

The telephone sets will be collected at the DIS Warehouse at 2201 Brookwood Dr, Suite 104, Little Rock, AR.

**Nortel Telephone Set Repair/Refurbishing**

Item Number	Product Description		Cost/Unit
1	M5316 Business Set		\$49.00
2	M9316CW Single Line Sets w/CWCID		\$41.00
3	M5216 Business Set		\$48.00
4	M5208 Business Set		\$45.00
5	M522 Add-on Unit (for M5216/M5316)		\$45.00
6	M9417CW Two Line Set		\$43.00

**Cisco IP Telephone Set Repair/Refurbishing**

Item Number	Product Description		Cost/Unit
1	Cisco 7940		\$64.00
2	Cisco 7941		\$64.00
3	Cisco 7960		\$69.00
4	Cisco 7961		\$69.00
5	Cisco7912		\$54.00
6	Cisco 7970		\$83.00
7	Cisco 7971		\$88.00